




A - Surface and assay map of Lucky Lodge mine, sec. 6, T.17N., R. 23W. and sec. 31, T. 18 N., R. 23 W, Seepay Creek mining district.




B - Surface map of New Deal mine, sec 19, T. 18 N., R. 23W, Seepay Creek mining district, showing geochemical traverses and graphed anomalies.



D - Geologic mine map of Ambassador mine, SE 1/4 sec. 4, T. 23 N., R. 32 W, Trout Creek mining district.



C - Map showing New Deal adit, sec. 19, T. 18 N., R. 23 W, Seepay Creek mining district.



E - Longitudinal projection of the Jack Waite mine, Sanders County, Montana and Shoshone County, Idaho.